

FIGURE 1(PRIOR ART)



FIGURE 2



FIGURE 3



FIGURE 4A



FIGURE 4B



FIGURE 5



FIGURE 6


71
Fix the image capturing device and the document glass; set the lens movable between tne image capturing device and the document glass
72
Place the calibration device on the document glass; connect the adjusting device to the image capturing device
73
Read values of a right side horizontal MTF, a right side vertical MTF, a left side horizontal MTF and a left side vertical MTF, from the adjusting device
74
Calculate the values of block 73 and generate a referencing parameter; display the referencing parameter in order to inform the assembling technician
75
Adjust the position of lens to change the value of the referencing parameter
76
Whether the referencing parameter achieves the maximum value?
No
Yes
77
Fix the position of lens

FIGURE 7